

Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 1
Photo Filename P6220094.JPG
Date/Time 6/22/2010
9:14:06 AM
Photographer Jamie Paulin

Description

Hanson Plating Machine trench. Waste water from plating line was collected in trench and was manually pumped into WWT unit. Line had not been in operation since January 2010.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 2
Photo Filename P6220095.JPG
Date/Time 6/22/2010
9:14:18 AM
Photographer Jamie Paulin

Description

Hanson Plating Machine trench. Waste water from plating line was collected in trench and was manually pumped into WWT unit. Line had not been in operation since January 2010. Liquid was located inside of trench at time of inspection.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 3
Photo Filename P6220096.JPG
Date/Time 6/22/2010
9:16:20 AM
Photographer Jamie Paulin

Description

Hanson Plating Machine. Materials were being stored inside of totes located near plating line. Plating line had not been used since January 2010.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 4
Photo Filename P6220097.JPG
Date/Time 6/22/2010
9:19:46 AM
Photographer Jamie Paulin

Description

Open bucket of material located on trench near the E-coat line. E-coat line was in operation 1 or 2 shifts per month.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 5
Photo Filename P6220098.JPG
Date/Time 6/22/2010
9:21:08 AM
Photographer Jamie Paulin

Description

Trench located near E-coat line. Trench collected waste water to be pumped into WWT unit periodically.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 6
Photo Filename P6220099.JPG
Date/Time 6/22/2010
9:21:18 AM
Photographer Jamie Paulin

Description

Open bucket of material located on trench near the E-coat line. E-coat line was in operation 1 or 2 shifts per month.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 7
Photo Filename P6220100.JPG
Date/Time 6/22/2010
9:27:12 AM
Photographer Jamie Paulin

Description

E-coat line.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 8
Photo Filename P6220101.JPG
Date/Time 6/22/2010
9:27:26 AM
Photographer Jamie Paulin

Description

3 open buckets of un-identified material were being stored on the floor near E-coat line. Spider webs/cob webs were located inside of buckets.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 9
Photo Filename P6220102.JPG
Date/Time 6/22/2010
9:27:34 AM
Photographer Jamie Paulin

Description

3 open buckets of un-identified material were being stored on the floor near E-coat line. Spider webs/cob webs were located inside of buckets.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 10
Photo Filename P6220103.JPG
Date/Time 6/22/2010
9:32:20 AM
Photographer Jamie Paulin

Description

Liquid was located on the floor near plating line. Open bucket of material was also located in this area.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 11
Photo Filename P6220104.JPG
Date/Time 6/22/2010
9:34:42 AM
Photographer Jamie Paulin

Description

55-gallon containers were being stored on a 5-tiered shelving unit. The 55-gallon containers were described as empty.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 12
Photo Filename P6220105.JPG
Date/Time 6/22/2010
9:34:52 AM
Photographer Jamie Paulin

Description

55-gallon containers and other types of containers were being stored on a 3-tiered shelving unit. The containers were described as storing raw materials.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 13
Photo Filename P6220106.JPG
Date/Time 6/22/2010
9:35:04 AM
Photographer Jamie Paulin

Description

3-tiered shelving unit. 55-gallon containers were being stored on the shelves. The containers were described as storing oil.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 14
Photo Filename P6220107.JPG
Date/Time 6/22/2010
9:35:58 AM
Photographer Jamie Paulin

Description

Raw material storage.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 15
Photo Filename P6220108.JPG
Date/Time 6/22/2010
9:37:26 AM
Photographer Jamie Paulin

Description

An open bucket, containing a material, was being stored in the raw material area on a pallet. A corroded metal lid was also being stored on the pallet.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 16
Photo Filename P6220109.JPG
Date/Time 6/22/2010
9:39:14 AM
Photographer Jamie Paulin

Description

A pit, with a grate, was located near the WWT unit waste water storage totes. A 4-inch thick un-identified solid material was located in the bottom of the pit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 17
Photo Filename P6220110.JPG
Date/Time 6/22/2010
9:39:36 AM
Photographer Jamie Paulin

Description

A pit, with a grate, was located near the WWT unit waste water storage totes. A 4-inch thick un-identified solid material was located in the bottom of the pit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 18
Photo Filename P6220111.JPG
Date/Time 6/22/2010
9:39:44 AM
Photographer Jamie Paulin

Description

A pit, with a grate, was located near the WWT unit waste water storage totes. A 4-inch thick un-identified solid material was located in the bottom of the pit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 19
Photo Filename P6220112.JPG
Date/Time 6/22/2010
9:40:06 AM
Photographer Jamie Paulin

Description

Totes that contained various plating line waste water prior to be treated in the WWT unit were being stored near the collection pit. The totes were not labeled or dated.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 20
Photo Filename P6220113.JPG
Date/Time 6/22/2010
9:43:04 AM
Photographer Jamie Paulin

Description

A pit, with a grate, was located near the WWT unit waste water storage totes. A 4-inch thick un-identified solid material was located in the bottom of the pit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 21
Photo Filename P6220114.JPG
Date/Time 6/22/2010
9:46:48 AM
Photographer Jamie Paulin

Description

3-tiered shelving unit storing 55-gallon containers. Containers were described as empty.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 22
Photo Filename P6220115.JPG
Date/Time 6/22/2010
9:48:36 AM
Photographer Jamie Paulin

Description

A plastic pallet was being stored near the WWT unit waste water storage totes. An unidentified liquid was located inside of the pallet.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 23
Photo Filename P6220116.JPG
Date/Time 6/22/2010
9:48:48 AM
Photographer Jamie Paulin

Description

A plastic pallet was being stored near the WWT unit waste water storage totes. An unidentified liquid was located inside of the pallet.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 24
Photo Filename P6220117.JPG
Date/Time 6/22/2010
9:48:58 AM
Photographer Jamie Paulin

Description

55-gallon containers were beings stored along the South wall. The containers were described as either empty or containing "working solutions."



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 25
Photo Filename P6220118.JPG
Date/Time 6/22/2010
9:50:38 AM
Photographer Jamie Paulin

Description

Totes were being stored and stacked along South wall. The totes were storing "working solutions."



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 26
Photo Filename P6220119.JPG
Date/Time 6/22/2010
9:52:58 AM
Photographer Jamie Paulin

Description

55-gallon containers were being stacked and stored next to the totes, along the South wall. The containers were described as being empty.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 27
Photo Filename P6220120.JPG
Date/Time 6/22/2010
9:56:10 AM
Photographer Jamie Paulin

Description

City water storage tank. Water to be used in
E-coat system.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 28
Photo Filename P6220121.JPG
Date/Time 6/22/2010
9:56:24 AM
Photographer Jamie Paulin

Description

10,000 gallon E-coat line crash tank to be used in emergencies. The tank was described as empty; however will be used to collect E-coat line material(s) in cases of emergencies.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 29
Photo Filename P6220122.JPG
Date/Time 6/22/2010
9:58:18 AM
Photographer Jamie Paulin

Description

A storm water reservoir was located outside on the East side of the facility. The grid covering was not safely placed on the reservoir.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 30
Photo Filename P6220123.JPG
Date/Time 6/22/2010
9:59:12 AM
Photographer Jamie Paulin

Description

Four trailers were located outside on the East side of the facility. Trailer 1 was empty.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 31
Photo Filename P6220124.JPG
Date/Time 6/22/2010
9:59:24 AM
Photographer Jamie Paulin

Description

Four trailers were located outside on the East side of the facility. Trailer 2 was empty.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 32
Photo Filename P6220125.JPG
Date/Time 6/22/2010
9:59:34 AM
Photographer Jamie Paulin

Description

Four trailers were located outside on the East side of the facility. Trailer 3 was being used as storage and contained Barrel line equipment.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 33
Photo Filename P6220126.JPG
Date/Time 6/22/2010
10:01:08 AM
Photographer Jamie Paulin

Description

Four trailers were located outside on the East side of the facility. Trailer 4 was being used as storage and contained fans and light fixtures.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 34
Photo Filename P6220127.JPG
Date/Time 6/22/2010
10:04:52 AM
Photographer Jamie Paulin

Description

Mid-City Plating name and logo was located on one of the trailers being stored outside on the East side of the facility.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 35
Photo Filename P6220128.JPG
Date/Time 6/22/2010
10:05:58 AM
Photographer Jamie Paulin

Description

The spill kit was being stored on the East side of the facility, not near hazardous waste storage. The spill kit container was being used as a garbage can at the time of the inspection.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 36
Photo Filename P6220129.JPG
Date/Time 6/22/2010
10:08:42 AM
Photographer Jamie Paulin

Description

Used oil was being stored inside of a pit that was located in the barrel row plating line room.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 37
Photo Filename P6220130.JPG
Date/Time 6/22/2010
10:08:52 AM
Photographer Jamie Paulin

Description

Used oil was being stored inside of a pit that was located in the barrel row plating line room.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 38
Photo Filename P6220131.JPG
Date/Time 6/22/2010
10:11:46 AM
Photographer Jamie Paulin

Description

Barrel Row and Strip Line. Containment pit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 39
Photo Filename P6220132.JPG
Date/Time 6/22/2010
10:12:22 AM
Photographer Jamie Paulin

Description

Barrel Row Line had been removed. Liquid was located on the floor. Equipment was being stored within the area.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 40
Photo Filename P6220133.JPG
Date/Time 6/22/2010
10:13:02 AM
Photographer Jamie Paulin

Description

Barrel Row Line had been removed. Liquid and other material were located on the floor. Equipment was being stored within the area.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 41
Photo Filename P6220134.JPG
Date/Time 6/22/2010
10:13:10 AM
Photographer Jamie Paulin

Description

Barrel Row Line had been removed. Liquid and other material were located on the floor. Equipment was being stored within the area. Rectangular equipment was being used as an oil bin.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 42
Photo Filename P6220135.JPG
Date/Time 6/22/2010
10:15:04 AM
Photographer Jamie Paulin

Description

Barrel Row line bath. No liquid was located inside; however dried blue/white material was still located inside of bath. (Barrel Row line had been discontinued and tank was going to be dismantled.)



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 43
Photo Filename P6220136.JPG
Date/Time 6/22/2010
10:15:12 AM
Photographer Jamie Paulin

Description

Broken fluorescent light bulb was located on the floor in the Barrel Row line room.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 44
Photo Filename P6220137.JPG
Date/Time 6/22/2010
10:15:56 AM
Photographer Jamie Paulin

Description

Zinc metal was being stored on a piece of fabric, located on the floor, near the Barrel Row line.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 45
Photo Filename P6220138.JPG
Date/Time 6/22/2010
10:17:50 AM
Photographer Jamie Paulin

Description

Barrel Row line equipment and pallet being stored.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 46
Photo Filename P6220139.JPG
Date/Time 6/22/2010
10:18:06 AM
Photographer Jamie Paulin

Description

Barrel Row line location. Liquids were being stored on the floor. Equipment was being stored within the area.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 47
Photo Filename P6220140.JPG
Date/Time 6/22/2010
10:18:24 AM
Photographer Jamie Paulin

Description

RIT dye being stored in an open 55-gallon container.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 48
Photo Filename P6220141.JPG
Date/Time 6/22/2010
10:20:00 AM
Photographer Jamie Paulin

Description

Un-identified liquid was being stored in a bath that had been used in the Barrel Row line plating process.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 49
Photo Filename P6220142.JPG
Date/Time 6/22/2010
10:20:10 AM
Photographer Jamie Paulin

Description

An oily liquid was being stored in an open 5-gallon bucket. The oil was described as hydraulic oil.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 50
Photo Filename P6220143.JPG
Date/Time 6/22/2010
10:21:34 AM
Photographer Jamie Paulin

Description

View of floor where the Barrel Row line was once in operation. Liquids and material were being stored on the floor. Various equipment was also being stored within the area.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 51
Photo Filename P6220144.JPG
Date/Time 6/22/2010
10:22:30 AM
Photographer Jamie Paulin

Description

WWT unit filter press. Approximately 1 cubic yard. F006 waste water treatment sludge. Container was open, not labeled with the words, "Hazardous Waste," and not labeled with an accumulation date.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 52
Photo Filename P6220145.JPG
Date/Time 6/22/2010
10:22:40 AM
Photographer Jamie Paulin

Description

WWT unit filter press. Approximately 1 cubic yard. F006 waste water treatment sludge. Container was open, not labeled with the words, "Hazardous Waste," and not labeled with an accumulation date.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 53
Photo Filename P6220146.JPG
Date/Time 6/22/2010
10:24:14 AM
Photographer Jamie Paulin

Description

WWT unit filter press. Approximately 1 cubic yard. F006 waste water treatment sludge. Container was open, not labeled with the words, "Hazardous Waste," and not labeled with an accumulation date.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 54
Photo Filename P6220147.JPG
Date/Time 6/22/2010
10:31:38 AM
Photographer Jamie Paulin

Description

WWT unit. Liquid was located on the floor and within trench and sump pit located underneath WWT unit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 55
Photo Filename P6220148.JPG
Date/Time 6/22/2010
10:31:46 AM
Photographer Jamie Paulin

Description

WWT unit. Liquid was located on the floor.
Blue material appeared to have leaked on the
outside of the tank labeled as, "Sulfuric
Acid."



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 56
Photo Filename P6220149.JPG
Date/Time 6/22/2010
10:34:58 AM
Photographer Jamie Paulin

Description

WWT unit. Liquid and debris were located on the floor. Trench and sump pit were located underneath the unit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 57
Photo Filename P6220150.JPG
Date/Time 6/22/2010
10:35:10 AM
Photographer Jamie Paulin

Description

WWT unit. Liquid was located on the floor.
300 gallon sump pit was located underneath
the unit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 58
Photo Filename P6220151.JPG
Date/Time 6/22/2010
10:35:16 AM
Photographer Jamie Paulin

Description

WWT unit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 59
Photo Filename P6220152.JPG
Date/Time 6/22/2010
10:36:20 AM
Photographer Jamie Paulin

Description

Zinc plating line. Process causes a continual spill of alkaline cleaner. Kitty litter was being placed on top of spilled material onto the floor on a continual basis. The kitty litter mix was being stored on the floor.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 60
Photo Filename P6220153.JPG
Date/Time 6/22/2010
10:36:42 AM
Photographer Jamie Paulin

Description

Zinc plating line. Process causes a continual spill of alkaline cleaner. Kitty litter was being placed on top of spilled material onto the floor on a continual basis. The kitty litter mix was being stored on the floor.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 61
Photo Filename P6220154.JPG
Date/Time 6/22/2010
10:41:10 AM
Photographer Jamie Paulin

Description

Material was being collected and stored within the containment pit below the zinc plating line.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 62
Photo Filename P6220155.JPG
Date/Time 6/22/2010
10:41:18 AM
Photographer Jamie Paulin

Description

Material was being collected and stored within the containment pit below the zinc plating line. Material also was being collected and stored on the floor. Corrosion was evident on the surface of the floor.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 63
Photo Filename P6220156.JPG
Date/Time 6/22/2010
10:42:50 AM
Photographer Jamie Paulin

Description

Material was being collected and stored within the containment pit below the zinc plating line. Material also was being collected and stored on the floor.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 64
Photo Filename P6220157.JPG
Date/Time 6/22/2010
10:43:00 AM
Photographer Jamie Paulin

Description

Material was being collected and stored within the containment pit below the zinc plating line. Material also was being collected and stored on the floor. Corrosion was evident on the surface of the floor.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 65
Photo Filename P6220158.JPG
Date/Time 6/22/2010
10:45:26 AM
Photographer Jamie Paulin

Description

Chromate solution. "Working Solution."



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 66
Photo Filename P6220159.JPG
Date/Time 6/22/2010
10:48:16 AM
Photographer Jamie Paulin

Description

Laboratory water.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 67
Photo Filename P6220160.JPG
Date/Time 6/22/2010
10:54:16 AM
Photographer Jamie Paulin

Description

Trench located on the floor in between rooms. Red un-identified red liquid was being stored within the trench. Pipes were located inside of the trench and were not connected from the exposed ends.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 68
Photo Filename P6220161.JPG
Date/Time 6/22/2010
10:54:24 AM
Photographer Jamie Paulin

Description

Zinc plating line. Liquid was located on floor near the line. Hoses and equipment were also located on the floor.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 69
Photo Filename P6220162.JPG
Date/Time 6/22/2010
10:54:46 AM
Photographer Jamie Paulin

Description

Trench located on the floor in between rooms. Red un-identified red liquid was being stored within the trench. Pipes were located inside of the trench and were not connected from the exposed ends.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 70
Photo Filename P6220163.JPG
Date/Time 6/22/2010
10:58:30 AM
Photographer Jamie Paulin

Description

Various equipment and raw material storage.
Located on South/West side of facility.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 71
Photo Filename P6220164.JPG
Date/Time 6/22/2010
10:59:20 AM
Photographer Jamie Paulin

Description

Zinc plating line. Liquid was located on the floor near the plating line.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 72
Photo Filename P6220165.JPG
Date/Time 6/22/2010
10:59:28 AM
Photographer Jamie Paulin

Description

Tank storage of "working solution."



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 73
Photo Filename P6220166.JPG
Date/Time 6/22/2010
11:00:12 AM
Photographer Jamie Paulin

Description

Containment pit was located underneath zinc plating line. Kitty litter was being used to absorb spilled material.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 74
Photo Filename P6220167.JPG
Date/Time 6/22/2010
11:00:46 AM
Photographer Jamie Paulin

Description

Liquids were being stored on the floor and within the containment pit of the zinc plating line.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 75
Photo Filename P6220168.JPG
Date/Time 6/22/2010
11:02:42 AM
Photographer Jamie Paulin

Description

Liquid was located on the floor of the South/West of the facility.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 76
Photo Filename P6220169.JPG
Date/Time 6/22/2010
11:03:32 AM
Photographer Jamie Paulin

Description

Un-identified material and equipment was located on the floor of the South/West side of the facility.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 77
Photo Filename P6220170.JPG
Date/Time 6/22/2010
11:05:32 AM
Photographer Jamie Paulin

Description

Water tank located near the zinc plating line.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 78
Photo Filename P6220171.JPG
Date/Time 6/22/2010
11:05:38 AM
Photographer Jamie Paulin

Description



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 79
Photo Filename P6220172.JPG
Date/Time 6/22/2010
11:05:44 AM
Photographer Jamie Paulin

Description

West side of zinc plating line. Red liquid was located in containment pit of line. Material was also being accumulated and stored on the floor near the line.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 80
Photo Filename P6220173.JPG
Date/Time 6/22/2010
11:05:56 AM
Photographer Jamie Paulin

Description

Floor surrounding zinc plating line, located in the South/West room. Debris and material were located on the floor surrounding line.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 81
Photo Filename P6220174.JPG
Date/Time 6/22/2010
11:08:14 AM
Photographer Jamie Paulin

Description

Hazardous waste storage area. No hazardous waste was being stored in this area at the time of the inspection.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 82
Photo Filename P6220175.JPG
Date/Time 6/22/2010
11:10:06 AM
Photographer Jamie Paulin

Description

F008 hazardous waste from plating process was being stored in a 55-gallon container as a satellite accumulation area (SAA) container. However, container was not being stored at or near point of operation and was not labeled correctly.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 83
Photo Filename P6220176.JPG
Date/Time 6/22/2010
11:10:14 AM
Photographer Jamie Paulin

Description

Hazardous waste storage area. SAA 55-gallon container, F008, was not being stored at or near point of operation and was not labeled correctly.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 84
Photo Filename P6220177.JPG
Date/Time 6/22/2010
11:12:58 AM
Photographer Jamie Paulin

Description

SAA 55-gallon container, F008, was not being stored at or near point of operation and was not labeled correctly.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 85
Photo Filename P6220178.JPG
Date/Time 6/22/2010
11:13:56 AM
Photographer Jamie Paulin

Description

Roll-off container was located outside on the North/West side of facility. Roll-off was filled to top of container with F006 hazardous waste. Lid was not completely closed. No hazardous waste label, or date of accumulation was located on container.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 86
Photo Filename P6220179.JPG
Date/Time 6/22/2010
11:14:04 AM
Photographer Jamie Paulin

Description

Roll-off container being stored outside on North/West side of facility. Lid was not completely closed on container. F006 hazardous waste was filled to top of container.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 87
Photo Filename P6220180.JPG
Date/Time 6/22/2010
11:14:12 AM
Photographer Jamie Paulin

Description

Roll-off container was located outside on the North/West side of facility. Roll-off was filled to top of container with F006 hazardous waste. Lid was not completely closed. No hazardous waste label, or date of accumulation was located on container.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 88
Photo Filename P6220181.JPG
Date/Time 6/22/2010
11:20:34 AM
Photographer Jamie Paulin

Description

F006 hazardous waste was located on the outside of the roll-off container and on the ground.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 89
Photo Filename P6220182.JPG
Date/Time 6/22/2010
11:20:46 AM
Photographer Jamie Paulin

Description

F006 hazardous waste was located on the outside of the roll-off container and on the ground.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 90
Photo Filename P6220183.JPG
Date/Time 6/22/2010
11:22:28 AM
Photographer Jamie Paulin

Description

F006 hazardous waste was located on the outside of the roll-off container and on the ground.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 91
Photo Filename P6220184.JPG
Date/Time 6/22/2010
11:24:04 AM
Photographer Jamie Paulin

Description

Trench with a grate, located in maintenance room, on West side of facility, was located within the floor. Liquid was being stored within the pit. Cleaner collects inside of grate and is pumped to WWT unit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 92
Photo Filename P6220185.JPG
Date/Time 6/22/2010
11:24:10 AM
Photographer Jamie Paulin

Description

Trench with a grate, located in maintenance room, on West side of facility, was located within the floor. Liquid was being stored within the pit. Cleaner collects inside of grate and is pumped to WWT unit.



Photographs for Mid City Plating Company CEI 6/22/2010

Media: RCRA

Disk Number 1
Photo Number 93
Photo Filename P6220186.JPG
Date/Time 6/22/2010
11:28:40 AM
Photographer Jamie Paulin

Description

Trench with a grate, located in maintenance room, on West side of facility, was located within the floor. Liquid was being stored within the pit. Cleaner collects inside of grate and is pumped to WWT unit.

